

**CUSTOMER:**

Hydro-Eko

**PROJECT:**

Vestas V-80 (2 MW) wind generator installation

**WHERE:**

Rymanov (Rymanów), Poland

**INVOLVED PERSONNEL:**

Wind blade inspection and repair technicians

**PERIOD:**

2013

**SCOPE OF WORKS:**

1. Inspection of 3 wind generator blades (length of each 39 m) after their transportation to the installation place.
2. Preparing the inspection report and the technology of blades repair.
3. Repair of wind generator blades.
4. Wind generator blades inspection after installation and report submission on the absence of damage.



